

## **LEGEND**

ESC CMP V

**CUMULATIVE IMPACT SEDIMENT** 

## **MONITORING STATIONS**

- CAPPED PIT STATION
- **NEAR-FIELD STATION**
- MID-FIELD STATION
- FAR-FIELD STATION
- ★ MA WAN STATION

	1				
				-	
ŀ				-	
P1	APR 2021	KN			
Rev	Date	Drawn	Description	Ch'k'd	App'd

MOTT MACDONALD

3/F International Trade Tower 348 Kwun Tong Road Kwun Tong, Kowloon Hong Kong T +852 2828 5757 F +852 2821823 W mottmac.com




AGREEMENT NO. CE 59/2020 (EP) **ENVIRONMENTAL MONITORING AND AUDIT** FOR DISPOSAL FACILITY TO THE EAST OF SHA CHAU (2021-2026)
- INVESTIGATION

**CUMULATIVE IMPACTS SEDIMENT QUALITY MONITORING STATIONS** FOR ESC CMPS
(BEFORE COMPLETION OF CAPPING AT Vd)

Designed	Eng check	
Drawn	Coordination	
Dwg check	Approved	
Scale at A3	Status	Rev

FIGURE 4.2A





## **LEGEND**

SC CMP V

ESC USABLE AREA 1

## **CUMULATIVE IMPACT SEDIMENT MONITORING STATIONS**

- CAPPED PIT STATION
- **NEAR-FIELD STATION**
- MID-FIELD STATION
- FAR-FIELD STATION
- ★ MA WAN STATION

	1				
				-	
ŀ				-	
P1	APR 2021	KN			
Rev	Date	Drawn	Description	Ch'k'd	App'd

MOTT MACDONALD

3/F International Trade Tower 348 Kwun Tong Road Kwun Tong, Kowloon Hong Kong T +852 2828 5757 F +852 2821823 W mottmac.com



AGREEMENT NO. CE 59/2020 (EP) **ENVIRONMENTAL MONITORING AND AUDIT** FOR DISPOSAL FACILITY TO THE EAST OF SHA CHAU (2021-2026)
- INVESTIGATION

**CUMULATIVE IMPACTS SEDIMENT QUALITY MONITORING STATIONS** FOR ESC CMPS
(AFTER COMPLETION OF CAPPING AT Vd)

Designed		Eng check			
Drawn		Coordination			
Dwg check		Approved			
Scale at A3	Status	Status		Rev	
II .					

FIGURE 4.2B