

Mott MacDonald | Agreement No. CE59/2020(EP) Environmental Monitoring and Audit for Disposal Facility to the East of Sha Chau (2021-2026) – Investigation Monthly EM&A Report for Contaminated Mud Pits to the East of Sha Chau – November 2022

Appendix C. Graphical Presentations



Routine Water Quality Monitoring for ESC CMP V - November 2022


Figure 1: Level of pH recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in November 2022



Routine Water Quality Monitoring for ESC CMP V - November 2022


Figure 2: Level of Dissolved Oxygen (DO) (% saturation; mean + SD¹) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in November 2022

¹ The mean and standard deviation (SD) for in-situ data are the mean and SD for water columns within the area.



Routine Water Quality Monitoring for ESC CMP V - November 2022

Figure 3: Concentration of Dissolved Oxygen (DO) (mg/L; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in November 2022



Routine Water Quality Monitoring for ESC CMP V - November 2022

Figure 4: Level of Temperature (°C; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in November 2022

¹ The mean and standard deviation (SD) for in-situ data are the mean and SD for water columns within the area.






Figure 5: Level of Salinity (ppt; mean + SD¹) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in November 2022



Routine Water Quality Monitoring for ESC CMP V - November 2022


Figure 6: Level of Turbidity (NTU; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in November 2022

¹ The mean and standard deviation (SD) for in-situ data are the mean and SD for water columns within the area.




Routine Water Quality Monitoring for ESC CMP V November 2022

Figure 7: Concentration of Arsenic, Copper, Nickel, and Zinc (µg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP V in November 2022




Routine Water Quality Monitoring for ESC CMP V November 2022

Figure 8: Concentration of Cadmium, Chromium, Lead, Mercury, and Nickel, (µg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP V in November 2022




Routine Water Quality Monitoring for Nutrients - November 2022

Figure 9: Concentration of Total Inorganic Nitrogen (TIN) and Ammonia Nitrogen (NH3-N) (mg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP V in November 2022




Routine Water Quality Monitoring for Biochemical Oxygen Demand (BOD5) -November 2022







Routine Water Quality Monitoring for Suspended Solids - November 2022

Μ





Pit Specific Sediment Chemistry for Metal and Metalloid Contaminants at ESC CMP Vb - November 2022






Μ










Μ




(mg/kg dry weight; mean + SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vb in November 2022








Μ





Appendix C - 9