Annex C

Graphical Presentations




Figure 1: Level of pH recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in July 2019.




Figure 2: Level of Dissolved Oxygen (DO) (% saturation; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in July 2019.

Date: August 2019






Figure 3: Concentration of Dissolved Oxygen (DO) (mg/L; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in July 2019.

Routine Water Quality Monitoring for ESC CMP V - July 2019 35.00 25.00 20.00 10.00 Reference Impact Station Reference Impact Station

Figure 4: Level of Temperature (°C; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in July 2019.

Source: H:\Team\EM\GMS Projects\0400720 CEDD CMP EM&A 2017-2020\02 Deliverable\05 CMP Monthly Report\July 2019)

Date: August 2019






Figure 5: Level of Salinity (ppt; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in July 2019.

Routine Water Quality Monitoring for ESC CMP V - July 2019 9.00 8.00 7.00 6.00 Turbidity (NTU) 5.00 4.00 3.00 2.00 1.00 0.00 Intermediate Reference Impact Ma Wan Station

Figure 6: Levels of Turbidity (NTU; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in July 2019.

Source: H:\Team\EM\GMS Projects\0400720 CEDD CMP EM&A 2017-2020\02 Deliverable\05 CMP Monthly Report\July 2019)

Date: August 2019






Figure 7: Concentration of Arsenic, Chromium, Nickel, Lead, Copper and Zinc (μg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP V in July 2019.




Figure 8: Concentration of Total Inorganic Nitrogen (TIN) and Ammonia Nitrogen (NH3-N) $(\mu g/L; mean + SD)$ in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP V in July 2019.

Source: H:\Team\EM\GMS Projects\0400720 CEDD CMP EM&A 2017-2020\02
Deliverable\05 CMP Monthly Report\July 2019)

Date: August 2019

Environmental
Resources
Management

ERM




Figure 9: Level of Biochemical Oxygen Demand (BOD₅) (mg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP V in July 2019.




Figure 10: Concentration of Suspended Solids (SS) (mg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP V in July 2019

Date: August 2019






Figure 11: Concentration of Metals and Metalloid (Cr, Cu, Ni, Pb, Zn, As; mg/kg dry weight; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in July 2019.




Figure 12: Concentration of Metals (Cd, Hg, Ag; mg/kg dry weight; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in July 2019.

Date: August 2019






Figure 13: Concentration of Total Organic Carbon (TOC) (mg/kg dry weight; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in July 2019.




Figure 14: Concentration of Tributyltin (TBT) (µg TBT/kg; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in July 2019.

Date: August 2019

